

# Photos RPM, OSC, CIC, ODEQ visit to Wilcox Oil Co Superfund Site

March 20, 2014



9612521

# Church exterior



# Church building interior

**Notice wood ceiling, walls, carpet.**

**Building is empty, not in use.**



# Church building interior

**Carpet, wall paper, paint**



**Storage area**





# Church exterior

**Some ground bare spots, see  
next slides**



**Slope next to creek**



# Closer look of “bare spots”





# More “bare spots”, creek behind those shrubs



# Creek next to the Church property





# Creek sediments



# The Church well

the well plug is the round red thing  
inserted in the well pipe





# In a residential property (former tank farm area)





Random spots with black tar, asphaltic  
like, oily material





# Closer look



Wilcox Oil Co Superfund Site - 3/20/2014



Residential property, these oily, tar like, asphalt like spots are scattered at random

